

METRO INDUSTRIAL WASTE
FIELD INSPECTION REPORT

LDWGF 12.3.54

10/07/92

DATE: 10/7/92

TIME: 2:05 pm

INVESTIGATOR: BAZ STEVENS

COMPANY NAME: LONE STAR INDUSTRIES

ADDRESS OR PLANT DESCRIPTION:
5975 E. Marginal Way S.
Seattle, WA

METRO PERMIT: No. 7529 IW Flow 27,975 Category Metro NA
Ex. date 9-20-93

INSPECTION/TYPE/PURPOSE: unannounced scheduled
new company complaint spill
explanation:
Annual S.I.U. Inspection.

LAST METRO ACTIONS (TYPE/DATE): inspection 12-6-91
sample None
violation None
enforcement None

NATURE OF OPERATION:
Mfr. & distribution of ~~concrete~~ concrete

number of employees:

PERSON CONTACTED ONSITE: Darrell Herman / Mike Patricelli / Taylor Walker
title Plant Superintendent / Supervisor / Laborer

PLANT OR PROCESS AREAS INSPECTED:

Warehouse
Shop
Truck Wash
Truck Load (Redi Mix)
Filter / Water Reuse / Water Treatment
general housekeeping = good ☒ fair ☐ poor

OBSERVED DISCHARGES TO METRO

cleaning machinery dysfunctional part 4 days.
Excess accumulated water (as a result of storm water accumulation) in pH adjusted (minimally acid)
by one discharge to Metro.

non-contact cooling water? yes ☒ no ☐ GPD

USEPA SF



1270098

PRETREATMENT SYSTEM:

type filter press
flow-thru batch
O + M manual available? No Reviewed? other
condition/operation = good (X) fair poor
change since last inspection

comments

Filter press clogging a bit due to cement additive used for current project.
This is expected to disappear when usual cement is returned to.

SPILL PREVENTION:

good fair poor N/A
conditions of berms: good fair poor N/A
floor drains in chemical areas? open closed N/A
ASPP: available? reviewed? (N/A)
Slug discharge control plan: available? reviewed? (N/A)

WASTE STREAMS TO SURFACE/GROUNDWATER:

Storm water on yards east side, outside of process area, drains to
Dumrich via oil/water separator.

CHEMICAL/WASTE STORAGE AREAS:

condition good (fair) poor
comment

Shop has several 55-gallon drums of dangerous liquids
without 2^o containment. Behind shop (east fence), drums of new product are
stored w/out cover/2^o containment, as are a few drums ^{w/cover} on SE corner of
bldg. These must be stored under cover with 2^o containment. Currently it
seems they may impact small ^{sewer?} ~~creaking~~ drains on the SE and NE corners of this shop bldg.

HAZARDOUS WASTE DRUMS/LABELS/MANIFESTS:

OK? N/A

WAD #

Problems

See above.

INSPECTION RESULTS

COMPLIED WITH METRO PERMIT? Yes No N/A
comment

PROBLEMS FOR WDOE REFERRAL? Yes No N/A
priority: ASAP High Medium Low
type: haz. waste storage surface/groundwater
see items no.:

referral date/person:

via: phone report ccd letter

RECOMMENDED ACTION BY METRO: Yes None
priority: ASAP High Medium Low
comments:

- check that 2^o containment/covers are improved.
- Issue DA. at Permit renewal time, should NPDES permit not materialize

ADDITIONAL COMMENTS:

check back w/in month for:

- improved legend 2^o containment/covers
- info on NPDES developments.

* Visit ~~low~~ Star NW plant on W. Marginal Way
Apparently there is truck moving activity.